

**LightSystem Fiber - Multimode 50/125 OM2**

Please be advised that Siemon has discontinued the LightSystem Multimode 50/125um OM2 product lines and replaced them with XGLO Multimode 50/125um OM3. To help assist in the transition, replacement part numbers have been identified in the tables below. We will accept LightSystem 50/125um OM2 orders until inventory is depleted.

**AFFECTED PRODUCTS**

• Plug and Play Trunks- MTP, MTP-LC	• Pigtailed- LC, SC, ST
• Plug and Play Modules- MTP, MTP-LC	• Trunks- LC, SC, ST
• Fusion Splice Modules- LC	• XLR8 Connectivity- LC, SC
• Jumpers- LC, SC, ST	• Bulk Fiber Cable

<b>Plug and Play Trunks: MTP-MTP, MTP-LC</b>	
<b>LightSystem OM2 Part Number</b>	<b>XGLO OM3 Replacement Part Number</b>
FR(XX)-5(X)(XXX)(X)-(X)	FR(XX)-5L(X)(XXX)-(X)
T(X)(X)(X)5(X)(XX)LC(XXX)(X)	T(X)(X)(X)5L(XX)LC(XXX)(X)

<b>Plug and Play Modules: MTP-MTP, MTP-LC</b>	
<b>LightSystem OM2 Part Number</b>	<b>XGLO OM3 Replacement Part Number</b>
PP2-(XX)-(XX)5-01(X)	PP2-(XX)-(XX)5L-01(X)
PPM-(XX)-(XX)5-01(X)	PPM-(XX)-(XX)5L-01(X)

<b>Fusion Splice Modules: LC</b>	
<b>LightSystem OM2 Part Number</b>	<b>XGLO OM3 Replacement Part Number</b>
FSM-(X)-(XX)-LC(X)5-01(X)	FSM-(X)-(XX)-LC(X)5L-01(X)

<b>Jumpers: LC,SC,ST</b>	
<b>LightSystem OM2 Part Number</b>	<b>XGLO OM3 Replacement Part Number</b>
FJ2-(XX)(XX)5MM-(XX)	FJ2-(XX)(XX)5L-(XX)AQ
FJ2-(XX)(XX)5MM-(XX)H	FJ2-(XX)(XX)5L-(XX)AH

<b>Pigtails: LC,SC,ST</b>	
<b>LightSystem OM2 Part Number</b>	<b>XGLO OM3 Replacement Part Number</b>
FP1B-(XX)5MM-(XX)	FP1B-(XX)5L-(XX)AQ
FP1B-(XX)MM-(XX)H	FP1B-(XX)5L-(XX)AH

LightSystem Multimode 50/125um OM2 – Global

December 18th 2015

**LightSystem - Multimode 50/125 OM2**

Fiber Trunks: LC,SC,ST	
LightSystem OM2 Part Number	XGLO OM3 Replacement Part Number
TF-(X)(X)C(X)(XX)(XX)(XXX)(X)	TF-(X)(X)L(X)(XX)(XX)(XXX)(X)

XLR8 Connectivity: LC,SC	
LightSystem OM2 Part Number	XGLO OM3 Replacement Part Number
FC1M-(XX)-5MM-B01	FC1M-(XX)5V-B12

Bulk Fiber Cable	
LightSystem OM2 Part Number	XGLO OM3 Replacement Part Number
9BB5(X)(XXXX)-T109A	9BB5(X)(XXXX)-T312A
9GD5(X)(XXXX)-T101A	9GD5(X)(XXXX)-T301A
9BC5(X)(XXXX)-T109A	9BC5(X)(XXXX)-T312A
9PE5(X)(XXXX)-T101A	9PE5(X)(XXXX)-T301A
9PF5(X)(XXXX)-T101A	9PF5(X)(XXXX)-T301A
9GG5L(XXXX)-T106M	9GG5L(XXXX)-T306M
9GD5L(XXXX)-T106M	9GD5L(XXXX)-T306M
9GG5H(XXXX)-T101M	9GG5H(XXXX)-T301M
9GD5H(XXXX)-T101M	9GD5H(XXXX)-T301M
9F5B(X)-(XXXX)(X.XX)	9F5LB(X)-(XXXX)(X.XX)
9F5D4-(XXXX)(X.XX)	9F5LD4-(XXXX)(X.XX)
9F5E4-(XXXX)(X.XX)	9F5LE4-(XXXX)(X.XX)

**RECOMMENDED ALTERNATE SOLUTIONS**

- LightSystem OM2 products have been replaced by the XGLO OM3 products. Please visit [www.siemon.com](http://www.siemon.com) for information, brochures and spec sheets related to the XGLO system.
- The XGLO products are higher performing, meeting Siemon's System warranty performance requirements.
- The vast majority of customers have already converted to XGLO products.

**The Americas**  
Watertown, CT USA  
Phone (1) 860 945 4200

**Europe/Middle East/Africa**  
Surrey, England  
Phone (44) 0 1932 571771

**Asia/Pacific**  
Shanghai, P.R. China  
Phone (86) 21 53850303

LightSystem Multimode 50/125um OM2 – Global

December 18th 2015